Suzanne Steab - July 2010 Inspection Reports

From:

Karl Houskeeper

To:

rnetz@emerytelcom.net

Date:

7/29/2010 1:18 PM

Subject:

July 2010 Inspection Reports

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: SCA July 2010.pdf; SPWF july 2010.pdf

Rusty,

Attached are the July 2010 inspection reports for SCA and SPWF.

Thanks, Karl



GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Renresentativ	es Present During the Inspection:
	Rusty Netz
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0070035		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, July 20, 2010		
Start Date/Time:	7/20/2010 9:00:00 AM		
End Date/Time:	7/20/2010 12:00:00 PM		
Last Inspection:	Wednesday, June 09, 2010		

Inspector: Karl Houskeeper,

Weather: Partly Cloudy, Temp. 81 Deg. F.

InspectionID Report Number: 2428

Accepted by: jhelfric 7/29/2010

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: ,

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Current	Acreages	Mineral Ownership	Types of Operations		
310.00	Total Permitted	☐ Federal	Underground		
202.00	Total Disturbed	☐ State	Surface		
5.50	Phase I	☐ County	☐ Loadout		
	Phase II	✓ Fee	Processing		
	Phase III	☐ Other	✓ Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Butch Hansen, Savage, accompanied Rusty Netz, SCA, and Karl Houskeeper, OGM, on the inspection.

Date

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 20, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Commont	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	Lvaluated	Not Applicable		
2.	Signs and Markers	<u> </u>		<u> </u>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		V	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 20, 2010

Page 3 of 3

2. Signs and Markers

A mine identification sign needs to be installed at the point of public access to the permit area or the area accessed off from the road to Columbia.

4.a Hydrologic Balance: Diversions

Minor maintenance work is needed on a few diversions throughout the dsturbed area.

7. Coal Mine Waste, Refuse Piles, Impoundments

Large erosion cuts on the face of the refuse pile, Northern side lower two terraces needs to be repaired.